STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL AND GAS

REPORT OF WELL ABANDONMENT

	Bakersfield,	California
	February 1, 1956	
Mr. Edward M. Easton, Agent MORIQUI EXPLORATION CO.		
1716 Oak Street Bakersfield, Calif.		
Your report of abandonment of Well No.	*KCL* 87-25	,
Sec. 25 , T. 268 , R. 258 , 10 B. 8	& М.,	field,
County, date	d November 1, 1955	, has been
examined in conjunction with records filed in	this office.	
A review of the reports and records shows t	hat the requirements of this	Division, which
are based on all information filed with it, hav	e been fulfilled.	
JCS: ew co-Company -Kern County Land Co. (2) -Gonservation Committee (2)		

Kern Co 2256 J.CS

E. H. MUSSER State Oil and Gas Supervisor

Deputy Supervisor

STATUS

Completed Producing
Recompleted Producing
Completed Abandoned
Uncompleted Abandoned 10-23-55
Idle

	RECCRDS	
	Received //_ 9-55 Needed	
	Well Summary	
4	Log & Core	
1	Lge_Sm Elec.Log(s)_Lge_Sm Direct.Survey	
	Other	
	Location	
	Release bond He	
	Hold bend Reason	
	Final letter 2-1-56 - 150b 2-1-56	
	1.70 1.21 CW	
	card	
	cw A K	
	Records Oix	
	//ccor c.=	
	11-10-5-5	
	11 100	
	1.05-	
	-/49	Enspection
	1111 for surtage pro	
	Hold for surface plug Surface J2. H.	
	Sortee 11. H.	

EASTON & SACRE
CONSULTING PETROLEUM ENGINEERS

FILL THIS

NK IN WITH TYPEWRITER. WRITE ON ONE SIDE OF BARS

E OF PAPE

STATE OF CALIFORNIA
DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL AND GAS

RECEIVED

NOV 9 1955

Total depth 7214° Plugged depth GEOLOGICAL MARKERS Junk None Cement plug 2697' = 2530° Olcese Sand (e-log) 600 Cement plug 1033° = 921° Cement plug from 10° below cellar floor to cellar floor. Commenced producing Never produced (date) Clean Oil below (cross out unnecessary words) Casing Record (Present Hole) Casing Record (Present Hole) Casing Record (Present Hole)	Agent) Casing
Elevation above sea level 385.9 Southeast corner of Section 25 Which is 10 feet above which is 10 feet above sea level 385.9	Agent) Casing
Location 9901 North and 3301 West from the All depth measurements taken from top of Kelly Bi Southeast corner of Section 25 which is 10 feet above which is 10 feet above the provisions of Chapter 93, Statutes of 1939, the information given herewith its a complete are record of the present condition of the well and all work done thereon, so far as can be determined from all available records. Date November 1, 1955 Easton & Sacre (Enginee and Garden of Section 25 (Superintendent)) Commenced drilling September 30, 1955 (Superintendent) Commenced plug 2697! — 2530! Olcose Sand (e-log) 600 (Commenced plug 1033! — 921! (Commenced producing Never produced (Green on anaccounty words) Commenced producing Never produced (Green on anaccounty words) Commenced producing Never produced (Green on anaccounty words) Cassod (Green on anaccounty words)	Agent) Agent) Casing
Title Plastary Commenced drilling September 30, 1955 Abandoned Commenced drilling September 30, 1955 Completed deciling October 23, 1955 Drilling tools R Total depth 7214 Plugged depth Genoted deciling October 23, 1955 Drilling tools R Junk None Cement plug 2697! - 2530! Olcese Sand (e-log) 600 Cement plug 1033! - 921! Cement plug 1033! - 921! Cement plug 104 below cellar floor to cellar floor Commenced producing Never produced (deas) Cless Oil Greeivy liacluding smultion Production after 30 days Casing Record (Present Hole) Casing Record (Present Hole) Casing Record (Present Hole) Casing Depth of Shoe Top of Casing of Casing Second Hand or Lapsveld of Casing Drilled Number of Sact of Cement Casing October 23, 1955 Drilling tools R Commenced deciling October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers Depth October 23, 1955 Drilling tools R Geological Markers October 24, 1955 Drilling tools R Geological Markers October 24, 1955 Drilling tools R Geological Markers Octobe	Agent) oble otary EPTH DO1 641
Easton & Sacre (Enginee Caraclegise) Commenced drilling September 30, 1955 Completed deciling October 23, 1955 Drilling tools of Recommenced drilling September 30, 1955 Completed deciling October 23, 1955 Drilling tools of Recommenced drilling September 30, 1955 Completed deciling October 23, 1955 Drilling tools of Recommenced deciling October 23, 1955 Drilling tools of Recommenced Plug 2697! — 2530! Olcose Sand (e-log) 600 Comment plug 1033! — 921! Comment plug from 10! below cellar floor to cellar floor to cellar floor. Commenced producing Never produced (dee) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words) Clean Oil Gravity Per Cent Water (cross out unsecurary words)	otary EPTH DO1 641
Commenced drilling September 30, 1955 Abandoned Completed decilieng October 23, 1955 Drilling tools of R Total depth 7214† Plugged depth GEOLOGICAL MARKERS DECIDING NONE Cement plug 2697! - 2530† Olcese Sand (e-log) 600 Cement plug 1033! - 921† Vedder Sand (e-log) 716 Cement plug from 10! below cellar floor to cellar floor. Commenced producing Never produced Geological Markers DECIDING Never DECIDING Never Produced Geological Markers DECIDING Never DECIDING Never Produced Geological Markers DECIDING Never DECIDIO NEVER DECI	otary EPTH DO1 641
Commenced drilling September 30, 1955 Abandoned Geometric Geological Markers Total depth 7214† Plugged depth Geometric Geological Markers Junk None Cement plug 2697! - 2530† Olcese Sand (e-log) 600 Cement plug 1033! - 921† Vedder Sand (e-log) 716 Cement plug from 10! below cellar floor to cellar floor to cellar floor of Commenced producing Never produced Geometric Grand Stephense (cross out unaccessary worlds) Cless Oil Gravity From Veter Water floor Mef. per day Tubing Pressure Initial production Produced Cless Oil Produced Mef. per day Tubing Pressure Casing Record (Present Hole) Casing Record (Present Hole) Casing Record (Present Hole)	otary EPTH DO1 641
Commenced drilling September 30. 1955 Completed drilling October 23. 1955 Drilling tools R Total depth 7214† Plugged depth. GEOLOGICAL MARKERS Junk None Cement plug 2697! = 2530† Olcese Sand (e-log) 600 Cement plug 1033! = 921! Cement plug from 10! below cellar floor to cellar floor o Commenced producing Never produced (date) (crose out unnecessary words) Clean Oil below (crose out unnecessary words)	otary EPTH DO † 64 †
Commenced producing Never produced Clean Oil Gravisy Clean Oil Gravisy Clean Oil Production Production Dry Hole Never Produced Production after 30 days CASING RECORD (Present Hole) Casing Depth of Shoe Top of Casing of Casing Second Hand of Casing Of Casing Depth of Shoe Top of Casing Second Hand Of Casing Of Casing Of Casing Depth of Shoe Top of Casing Second Hand Of Casing Of C	Casing
Commenced producing Never produced (deta) (cross out unnecessary words) Clean Oil bbl. per day Clean Oil including emulsion Mcf. per day Pressure Initial production Dry Hole Never Produced Production after 30 days CASING RECORD (Present Hole) Top of Casing Veight of Casing Second Hand or Lapweld of Casing Drilled Number of Sack of Centers.	
Commenced producing Nover produced (date) Clean Oil Gravity Clean Oil Per Cent Water including emulsion Production after 30 days CASING RECORD (Present Hole) Top of Casing Of Casing Of Casing Second Hand On Lapweld Of Casing Drilled Number of Sack of Cement	
Clean Oil bbl. per day Clean Oil bbl. per day Clean Oil clean Oil including emulsion Dry Hole Never Produced Production after 30 days CASING RECORD (Present Hole) Top of Casing (A. P. I.) Tubing Pressure Casing Second Hand Seamless of Casing Drilled Number of Sack of Centert	
Initial production Production after 30 days Casing Record (Present Hole) Casing Of Casing (A. P. I.) Depth of Shoe Top of Casing Of Casing Second Hand Or Lapweld Of Casing Drilled Of Cement	
Production after 30 days CASING RECORD (Present Hole) te of Casing Depth of Shoe Top of Casing Weight of Casing Second Hand Second Hand Or Lapweld Of Casing Drilled Of Cenient	Pressure
te of Casing Depth of Shoe Top of Casing Weight of Casing Second Hand or Lapweld of Casing Drilled Number of Sack of Centent	
(A. P. I.) Depth of Shoe lop of Casing of Casing Second Hand or Lapweld of Casing Drilled of Cement	
1-3/4" 997' Surface 42# New Smls. H-40 16" 775	Depth of Cementing if through perforations
	8
Perforations	
ize of Casing From To Size of Perforations Number of Rows Between Centers Method of P	erforations
ft. ft.	

SUBMIT IN DUPLICATE STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES



EIVED

DIVISION OF OIL AND GAS

.NOV 9 1955

History	of	Oil	or	Gas	W	ell	l
---------	----	-----	----	-----	---	-----	---

OAKERSFIELD, CALIFORNIA

OPERATOR Moriqui Exploration	Company FIELD	Famosa Area
Well No. "K.C.L." #87-25	, Sec. 25 , T.	26S., R. 25E., M.D. B. & M.
	Signed	
Date November 1, 1955	Tit	(President, Secretary or Agent)

It is of the greatest importance to have a complete history of the well. Use this form in reporting the history of all important operations at the well, together with the dates thereof, prior to the first production. Include in your report such information as size of hole drilled to cementing or landing depth of casings, number of sacks of cement used in the plugging, number of sacks or number of feet of cement drilled out of casing, depth at which cement plugs started, and depth at which hard cement encountered. If the well was dynamited, give date, size, position and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.

Contractors prepared location including 24' x 100' x 10' sump, 6' x 6' x 4-1/2' cellar with 6" concrete bottom and 20" conductor pipe concreted in 30" hole to depth of 24' below base of cellar.

John S. Hagestad Drilling Company, drilling contractors, moved in equipment, rigged up and commenced drilling operations at 2:00 a.m., September 30, 1955. Drilled 16" hole from surface to 998. Pulled out and ran back to bottom to condition hole for pipe.

Ran and cemented at 997', 25 joints of 11-3/4" casing (42#, Youngstown, H-40, Range 3, S.T.& C.) with 775 sacks of type "0" cement, last 100 sacks treated with 2% CaCl₂. Mixed 110# to 118# slurry in 45 minutes and displaced with 680 cubic feet (7' over theoretical) in 30 minutes. Used two top plugs, one rubber followed by wooden plug. Plug bumped under 700# pressure with cement in place at 1:10 a.m., October 1, 1955. Had good returns throughout with cement returns after 275 cubic feet. Used Baker open guide shoe and two Baker centralizers place 10' and 50' above shoe. Oil Well Cementing equipment used.

After standing cemented 8 hours, the casing was landed and the casing head installed. Welds were tested with 1500 p.s.i. for 10 minutes - OK. Double Shaffer and Regan bag packer blow-out prevention equipment was installed.

Tested Shaffer complete shut-off with 1000 p.s.i. for 30 minutes - OK. Ran pipe and tested pipe rams and Regan bag packer each with 1000 p.s.i. for 30 minutes - OK. Located top of cement at 993°. Drilled out cement, plug, and checked shoe at 997°. Drilled ahead in 10-5/8" hole to 1319°.

Drilled 10-5/8" hole to 4950', reduced hole and drilled 8-1/2" hole to 5100'. Circulated hole clean and conditioned mud.

Schlumberger electric log Run #1 - recorded from 997' to 5098'.

Date

1955

Sept 28 to Sept 29 Incl.

sept 29 to Oct 1 Incl.

Oct 2

to to Incl.

SUBMIT IN DUPLICATE STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES



OT O'L AND GAS EIVED .NOV 9 1955

DIVISION OF OIL AND GAS

History of Oil or Gas Well

PAREKSFIELD, CALIFORNIA

OPERATOR	Moriqui Exploration	Company	FIELD	Famosa A	rea
Well No	"K,C.L." #87-25	, Sec	25 , T.	26S., R. 25	5E., M.D. B. & M.
			Signed		
Date No	vember 1, 1955		Tit	:le	(President, Secretary or Agent)

It is of the greatest importance to have a complete history of the well. Use this form in reporting the history of all important operations at the well, together with the dates thereof, prior to the first production. Include in your report such information as size of hole drilled to cementing or landing depth of casings, number of sacks of cement used in the plugging, number of sacks or number of feet of cement drilled out of casing, depth at which cement plugs started, and depth at which hard cement encountered. If the well was dynamited, give date, size, position and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.

Mud weight 75# to 80#, viscosity 45 to 55 seconds, water loss reduced from 11.5cc/30 minutes to 6cc/30 minutes at 5100'. Surveys: at 998' 0°45', at 1317' 0°30', at 1517' 0°30', at 2343' 2°20', at 2530' 1°, at 2815' 1°50', at 3023' 1°00', at 3227' 1°10', at 3427' 1°00', at 3549' 0°45', at 3783' 1°30', at 3996' 1°50', at 4324' 1°30', at 4443' 0°45', at 4668' 1°30', at 4748' 1°50', at 4950' 1°20'.

Opened 8-1/2" hole to 10-5/8" hole from 4950' to 5100' and drilled ahead in 10-5/8" hole to 5200'. Drilled 8-1/2" hole from 5200' to 5350'. Mud weight 78#, viscosity 51 seconds, sand 2%, water loss 5.6cc/30 minutes, filter cake 2/32". Survey: at 5350' 1°55'.

Ran Schlumberger electric log Run #2 and recorded from 50981 to 53481.

Johnston Formation Test interval 5208' to 5350'. Ran M.O. Johnston Hydraulic tester on 4-1/2" full hole drill pipe with 200' water cushion, Sutliff jars, Homco safety joint, left hand joint below packer. Used dual "bob-tailed" packers with lower packer set at 5208'. Used 62' of 4-1/2" drill pipe on bottom with perforated tail pipe on top as tail below packer. Opened valve at 3:50 p.m. for 45 minute test. Had medium steady to light steady blow at end of test. No gas odor. Recovered net rise of 120' of drilling fluid. No oil or gas shows. Flow pressure 200 p.s.i.

Ran 10-5/8" bit and opened 8-1/2" hole to 10-5/8" hole from 5200' to 5350'. Drilled ahead in 10-5/8" hole from 5350' to 5885'. Reduced hole and drilled 8-1/2" hole from 5885' to 6026'. Ran 7-5/8" Allen conventional core barrel with rock head and cored from 6026' to 6054'. Recovered 28'. Mud weight 85#, viscosity 60 seconds, water loss 5cc/30 minutes, filter cake 2/32", sand 2%. Survey: at 6026' 2000'.

Ran Schlumberger electric log Run #3 and recorded from 5348' to 6048'.

Ran 10-5/8" bit and opened 8-1/2" hole to 10-5/8" hole from 5885; to 6010.

Opened 8-1/2" hole to 10-5/8" hole from 6010' to 6054' and drilled ahead to 7125'. Reduced hole size and drilled 7-5/8" hole from 7125' to 7186'. Mud weight 81#, viscosity 58 seconds, sand 3%, water loss 4.8cc/30 minutes, filter cake 2/32". Survey: at 6246' 2005', at 6510' 2000',

1955 Oct 3 to Oct 7 Incl. (Con't)

oct 8 to oct 9 Incl.

Oct. 10 to Oct. 16 Incl.

oct. 17

oct. 21

SUBMIT IN DUPLICATE STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES



NOV 9 1955

DIVISION OF OIL AND GAS

History of Oil or Gas Well

BAKERSFIELD, CALIFORNIA

OPERATOR	Moriqui Exploratio	n CompanyField	Famosa Are	э.а
Well No	"K.C.L." #87-25	, Sec. 25 , T. 2	26s. , R. 251	E., M.D. B. & M.
		Signed		
Date Nov	ember 1, 1955	Title	6	(President, Secretary or Agent)

It is of the greatest importance to have a complete history of the well. Use this form in reporting the history of all important operations at the well, together with the dates thereof, prior to the first production. Include in your report such information as size of hole drilled to cementing or landing depth of casings, number of sacks of cement used in the plugging, number of sacks or number of feet of cement drilled out of casing, depth at which cement plugs started, and depth at which hard cement encountered. If the well was dynamited, give date, size, position and number of shots. If plugs or bridges were put in to test for water, state kind of material used, position and results of pumping or bailing.

1955 Oct. 17

at 6663' 1°45', at 7033' 1°30'. Circulated hole clean and ran 7-5/8" Allen conventional core barrel with rock head and cored from 7186' to 7214'. Recovered 28'. Total Depth 7214'.

to Oct. 21 Incl. (Cont'd)

Ran Schlumberger electric log Run #4 and recorded from 6048' to 7212'. Took eleven sidewall samples. Bridge plug 2697' to 2530'. Oilwell Cementers equalized 100 sacks type "0" cement through 4-1/2" full hole drill pipe (16.6# and 18.1#) hung at 2697'. All cement treated with 2% CaCl2. Pumped 15 cubic feet water ahead and behind. Displaced with 185 cubic feet mud. Cement in place at 4:40 a.m., October 22, 1955. After standing cemented four hours, the top of cement was located at 2530'. Plug supported 10 tens of weight. Location and hardness was witnessed and approved by Mr. John Hardoin, Engineer for the Division of Oil and Gas.

Bridge plug 1033' to 921' in process of abandonment. Equalized 75 sacks of Permanente type "0" cement through 4-1/2" full hole drill pipe hung at 1033'. Slurry all treated with 2% CaCl2. Pumped 15 cubic feet of water ahead and 5 cubic feet of water behind. Displaced with 60 cubic feet mud with cement in place at 11:40 a.m. After standing cemented four hours, located the top of firm cement at 921' where it supported 7 tons of weight.

Laid down drill pipe. Left hole filled with heavy mud below plugs. Surface plug from 14' below surface to 4' below surface was placed on top of 11-3/4" casing at 11:00 a.m., October 23, 1955. A 3/8" steel plate was welded on top of the 11-3/4" casing. Well abandoned.

Date 1955

oct. 22 to

Oct. 23 Incl.

SUBMIT IN DUPLICATE

STATE OF CALIFORNIA
DEPARTMENT OF NATURAL RESOURCES

NOV 9 1955

BAKERSFIELD, CALIFORNIA

DIVISION OF OIL AND GAS

LOG AND CORE RECORD OF OIL OR GAS WELL

Well No. "KCL" #87-25 Sec. 25 , T. 26S. , R. 25E. , M.D. B. & M.

Operator Moriqui Exploration Company Field Famosa Area

FORMATIONS PENETRATED BY WELL

DEPT	тн то						
Top of Formation	Bottom of Formstion	Thickness	Drilled or Cored	Recovery	DESCRIPTION		
60261	6054	281	Core #1	281	5' Siltstone, greenish gray, finely sandy, bentonitic in streaks, occasional hard cemented sandstone shells, poor 8 to 10° (?) dips. 23' Sand, "salt and pepper" cast, gray, generally very fine grained, locally medium grained, friable, apparent good porosity and permeability, numerous hard, tight kaolinitic streaks, worm borings, salty taste.		
7186	7214'	281	Core #2	281	14' Sand, gray, medium grained, massive, friable, predominately sub-angular grains, scattered mafic grains, good porosity and permeability. No odor, stain or cut. Sour odor, very spotty fleeting gas odor. No fluorescence. 1-1/2' Calcareous sandstone shell, hard, dense, scattered megafossil fragments. 12-1/2' Sand, gray as above. Core descriptions by: C. Edwards J. Decker Total Depth - 7214' Electric log to 7214' Abandoned October 22, 1955		
				-5-			

EASTON & SACRE CONSULTING PETROLEUM ENGINEERS

SUBMIT IN DUPLICATE

STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL AND GAS RECEIVED

DIVISION OF OIL AND GAS NOV 9 1955

LOG AND CORE RECORD OF OIL OR GAS WELLBAKERSFIELD, CALIFORNIA

Operator Moriqui Exploration Company Field Famosa Area

Well No. "KCL" #87-25 Sec. 25 , T. 268. , R. 25E. , M.D. B. & M.

DEP	тн то		Drilled	Recovery	DESCRIPTION
Top of Formation	Bottom of Formation	Thickness	or Cored	Recovery	
			SIDEWALL S	WALE DES	CRIPTION
		1	SIDEWALL 5	APIT III DIC	ONIT IIVA
		Depth			Description
		24951			Sand, green, fine grained, good porosity and permeability. No odor, stain or cut.
		27951			Clay, green with pockets or nests of gray sand. No odor, stain or cut.
		28271			Sand, green, fine grained, clay stringers, fair porosity and permeability. No odor, stain or cut.
		36651			Sand, green with green clay stringe clayey, mega fossil fragments tight. No odor, stain or cut
		37671			Sand, green, marly, hard, tight. No odor, stain or cut.
		5125' 5133'			No recovery.
		52081	1		Shale, brown. No odor, stain or cu
		5514'			Shale, brown. No odor, stain or co
		55321		5	No recovery.
		58931			Brown shale fragments. No odor, stain or cut.
		58971			Shale, brown. No odor, stain or co
		60531			Sand, gray, fine grained, friable, clean, fair to good porosity and permeability. No odor, stain or cut.

-6-

SUBMIT IN DUPLICATE

STATE OF CALIFORNIA
DEPARTMENT OF NATURAL RESOURCES

VECN OF OIL AND GAS

.NOV 9 1955

DIVISION OF OIL AND GAS

LOG AND CORE RECORD OF OIL OR GAS WELL BAKERSFIELD, CALIFORNIA

Operator Moriqui Exploration Company Field Famosa Area

Well No. "KCL" #87-25 Sec. 25 , T. 268. , R. 25E. , M.D. B. & M.

FORMATIONS PENETRATED BY WELL								
DEPT	н то		5.11.1					
Top of Formation	Bottom of Formation	Thickness	Drilled or Cored	Recovery	DESCRIPTION			
		<u>S</u> Depth	IDEWALL SA	MPLE DESC	RIPTION Description			
		62331			Sand, gray, calcareous, mega fossil fragments, hard, poor porosity and permeability. No odor, stain or cut.			
					Sidewall sample descriptions by: Mr. Jack Decker Mr. Chuck Edwards			
			•					
				- 7-				

STATE OF CALIFORNIA

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL AND GAS

Special Report on Operations Witnessed

No. T B 455-614 Mr. Edward M. Easton 1716 Oak Street Bakersfield Bakersfield, California October 28 1955 Agent for MORIQUI EXPLORATION COMPANY DEAR SIR: Operations at your well No. "K C I" 87-25 Sec. 25 , T. 26 S , R. 25 E , M.D. B. & M., Field, in Kern County, were witnessed, 1955. Mr. John Hardein , representative of the supervisor was present from 8:15 AM to 9:00 AM . There were also present T. Easton, Engineer: Dunham, Drilling Foreman. Present condition of well: 11-3/4" cem. 9971; TD 72141 plugged with cement 26971-25301. The operations were performed for the purpose of plugging the hale in the process of abandon-Easton Mr. reported: 1. A 10-5/8" hole was drilled from 997' to 7186' and a 7-5/8" hole to 7211'. 2. On October 20, 1955, 100 sacks of cement was pumped into the hole through 4-1/2" drill pipe hanging at 2697'. The inspector noted: that the cement plug at the reported depth of 2530' supported all of the weight of the drill pipe. THE LOCATION AND HARDNESS OF THE CEMENT PLUG AT THE REPORTED DEPTH OF 2530' ARE

ec - Company Kern Co. Land Co. (2)

JLH: jw

APPROVED.

E. H. MUSSER
State Oil and Gas Supervisor

By J.

Deputy

5440 9-54 17,850 ② SPO

STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL AND GAS REPORT ON PROPOSED OPERATIONS

No. P. B 455-719

Mr.	Edv	rard H.	Easto	m		
	171	6 Oak	Street			
	Bal	ersfie	ld. Ca	liforni	a	
Agent				LORATIO		PANY

Bakersfield Calif. October 27 19 55

DEAR SIR!

Your

proposal to abandon Well No. "KCIP 87-25

Kern

Section 25 , T. 26 S. R. 25 E. M.D.B. & M.

County,

dated Oct. 22 19 55, received Oct. 25 19 55, has been examined in conjunction with records filed in this office.

Present conditions as shown by the records and the proposal are as follows:

RECORDS in addition to, or at variance with those shown in the notice: The base of the fresh water sands as estimated from the electrical log is at 2650't.

THE NOTICE STATES:

"The present condition of the well is as follows:

1. Total depth: 7214'.

2. Complete casing record:

11-3/4" casing cemembed at 997". 10-5/8" hole to 7125'; 7-5/8" hole from 7125' to 7214'. Top of gray, barren Olcese sand was encountered at 6000' and top of gray, barren Vedder sand was encountered at 7166'. Cores, sidewall samples and electric log did not disclose any showings of oil and/ or gas.

3. Last produced: Dry hole - never produced. "

PROPOSAL

"The proposed work is as follows: (Confirming conversation Albright-Easton, October 21, 1955)

1. Plug with cement from 2600' to 2700'. Location and hardness of this plug to be witnessed by your department.

2. Plug with cement from 977' to 1017' across shoe of 11-3/4" casing which is located at 997'.

3. Fill 11-3/4" casing with cement from cellar floor (4' below ground level) to point 10° below cellar floor, and ABANDON well and location."

THE PROPOSAL, COVERING WORK ALREADY COMPLETED IN ACCORDANCE WITH PRIOR DECISION: AGREEMENT, IS APPROVED.

Bond No. 222604, dated 9-12-55 cc - Company MA:jw

E. H. MUSSER, State Oil and Gas Supervisor

By GG Peire Deputy

STATE OF CALIFORNIA DEPARTMENT OF NATURAL RESOURCES

RECEIVED

DIVISION OF OIL AND GAS

OCT 2 5 1955

Notice of Intention to Abandon Well

This notice must be given at least five days before work is to begin; one copy only BAKERSFIELD,			
BAKEKSFIELD	1 64	drii Omin	

Los Angeles Calif. October 22. DIVISION OF OIL AND GAS Bakersfield In compliance with Secs. 3228, 3229, 3230, 3231 and 3232, Ch. 93, Stat. 1939, notice is hereby given "KCL" #87-25 that it is our intention to abandon well No. T. 26S. R. 25E. M.D. B. & M. Sec. 25 Field. 22nd County, commencing work on the day 1955 October The present condition of the well is as follows: 72141. 1. Total depth. 2. Complete casing record. 11-3/4" casing cemented at 997'. 10-5/8" hole to 71251; 7-5/8" hole from 71251 to 72141. Top of gray, barren Olcese sand was encountered at 6000' and top of gray, barren Vedder sand was encountered at 7166'. Cores, sidewall samples and electric log did not disclose any showings of oil and/or gas. Dry hole - never produced. 3. Last produced. Gravity The proposed work is as follows: (Confirming conversation Albright-Easton, Oct. 21, 1955) Plug with cement from 2600! to 2700!. Location and hardness of this plug to be witnessed by your department. Plug with cement from 977' to 1017' across shoe of 11-3/4" 2. casing which is located at 997'. Fill 11-3/4" casing with cement from cellar floor (4' below ground level) to point 10' below cellar floor, and ABANDON well and location. Reference to file of date Moriqui Exploration Company (Name of Operator) US Map & Bond Book GS ADDRESS ONE COPY OF NOTICE TO DIVISION OF OIL AND GAS IN DISTRICT WHERE WELL IS LOCATED

STATE OF CALIFORNIA

DIVISION OF OIL AND GAS

Special Report on Operations Witnessed

	Mr. Edward M Easton	
	1716 Oak Street	Bakersfield Calif.
	Bakersfield, California	October 6 19 55
	Agent for MORIQUI EXPLORATION COMPANY	h / ufa-fa-
	DEAR SIR:	
	Operations at your well No. "KCL" 87-25 Field, in	Sec. 25 , T. 26 S , R. 25 E , M.D. B. & M., Kern
	on October 3 , 1955 Mr. John Harde	County, were witnessed
	from 3:15 PM to 3:45 PM . There were also pr	resent R. Wood, Drilling Foreman;
		A. L. Smith, Driller.
	Present condition of well: 11-3/4" cem. 997', T	[.D. 2530 (drilling)
		pecting the blow-out prevention equipment.
	Mr. Wood reported:	
	cement. Cement returned to the surface.	ing was cemented at 997 with 775 sacks of
	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at	dril blow-out preventer were each tested unde
е	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped	dril blow-out preventer were each tested unde
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr	dril blow-out preventer were each tested under 2530'. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe.
e	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe.
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick.
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe.
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick.
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick. Sure plug valve into the 11-3/4" casing below
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly. E BLOW-OUT PREVENTION EQUIPMENT AND INSTALLA	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Tound the 4-1/2" drill pipe. located outside the derrick. Sure plug valve into the 11-3/4" casing below
e ui	cement. Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Cound the 4-1/2" drill pipe. located outside the derrick. Sure plug valve into the 11-3/4" casing below TION ARE APPROVED.
e ui	Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick. Four plug valve into the 11-3/4" casing below TION ARE APPROVED. And A 186' will drill into Vedder @ 1300'± 6000' Top of Olcese, grey
e ui	Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick. Four plug valve into the 11-3/4" casing below TION ARE APPROVED. And A 186' will drill into Vedder @ 1300'± 6000' Top of Olcese, grey
e ui	Cement returned to the surface. The Shaffer double control gate and the Hy 1000 1b for 30 min. A 10-5/8" hole was being drilled ahead at a inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing around the controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly. E BLOW-OUT PREVENTION EQUIPMENT AND INSTALLA	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick. Four plug valve into the 11-3/4" casing below TION ARE APPROVED. And A 186' will drill into Vedder @ 1300'± 6000' Top of Olcese, grey
e ui	Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Found the 4-1/2" drill pipe. located outside the derrick. Four plug valve into the 11-3/4" casing below TION ARE APPROVED. And A 186' will drill into Vedder @ 1300'± 6000' Top of Olcese, grey
e ui	Cement returned to the surface. The Shaffer double control gate and the Hy 1000 lb for 30 min. A 10-5/8" hole was being drilled ahead at e inspector noted that the well was equipped uipment: A Shaffer double control gate for closing hole, and for closing around the 4-1/2" dr A Hydril blow-out preventer for closing ar The controls for the above equipment were A 2" mud fill-up line with a 2" high press the above equipment. A high pressure stopcock on the kelly.	dril blow-out preventer were each tested under 2530. I with the following blow-out prevention in the well with the drill pipe out of the rill pipe. Cound the 4-1/2" drill pipe. located outside the derrick. Sure plug valve into the 11-3/4" casing below TION ARE APPROVED.

DIVISION OF OIL AND GAS

REPORT ON PROPOSED OPERATIONS

No. P. B 455-630

蓝

Mr. Edward M. Easten

1516 Oak Street
Bakersfield, California
September 19
19 55

Agent for MORIQUI EXPLORATION COMPANY

DEAR SIR:

Your proposal to drill Well No. "K C I" 87-25

Section 25 T. 26 S. R. 25 B M.D.B. & M., Field, Keyn County

dated Scot. 12 19 55, received Scot. 13 19 55, has been examined in conjunction with records filed in this office.

Present conditions as shown by the records and the proposal are as follows:

THE NOTICE STATES:

"Legal description of lease: Section 25.

Location of Well: 990 North along section line and 330 West at right angles

to said line from the Southeast corner of Section 25. Elevation of ground above sea level 385.9' mat datum.

All depth measurements taken from top of Kelly bushing to be submitted later."

PROPOSAL:

"PROPOSED CASING PROGRAM

Size of Casing Inches A.P.I. 11-3/hm 7"	Weight 1,2// 23// 26//	Grade and H-h0 J-55 N-80		Surface	Bottom C 1000'± 5865'± or 7050'±	menting 1000'± 5865'± 7050'±	
	•••		(No				fresh water
5-1/2"	17#	3-55	Smls.	7850*± or 7030*±	5900*±		

Intended zone or zones of completion: Olcese or Vedder Zones. It is understood that if changes in this plan become necessary we are to notify you before running casing."

DECISION: THE PROPOSAL IS APPROVED PROVIDED THAT:

 Nad fluid consistent with good drilling practice shall be used and the column of mud fluid maintained at all times to the surface particularly while pulling the drill pipe.

2. The 11-3/4" casing shall be cemented with sufficient cement to fill all the space back of the casing.

3. Adequate blow-out prevention equipment shall be installed and maintained in operating condition at all times.

4. Any hole to be sidetracked in any oil or gas zone shall be filled with cement if possible.

E. H. MUSSER

State Oil and Gas Supervisor

By Continued on Page 2

Deputy



STATE OF CALIFORNIA



DIVISION OF OIL AND GAS

Report on Proposed Operations

No. P B 155-630
Page 2

MORIGUI EXPLORATION COMPANY

Well No. "K C IP 87-25

, Section 25 , T. 26 S , R. 25 B , M.D. B. & M.

5. THIS DIVISION SHALL BE NOTIFIED:

a. TO INSPECT the installed blow-out prevention equipment before drilling below 2000.

b. TO WITNESS a test of the 7" shut-off.

cc - Company
Easton
Kern Co. Land Co. (2)
Bond No. 222604, Dated 9-12-55
MBA: jw

R. D. BUSH, State Oil and Gas Supervisor

By T. Jew

Deputy

DIVISION OF OIL AND GAS RECEIVED SEP 14 1955

BAKEKSTIELD, CALIFORNIA



STATE OF CALIFORNIA

DEPARTMENT OF NATURAL RESOURCES

DIVISION OF OIL AND GAS

Notice of Intention to Drill New Well

This notice and surety bond must be filed before drilling begins

DIVISION OF OIL AND GAS TAFT. CALIFORNIA

Los Angeles	Calif.	September	1219	55

DIVISION OF OIL AND GAS In compliance with Section 3203, Division III, Article 4, Public Resources Code, notice is hereby given that it is "Kern County Land Co. " #87-25 our intention to commence the work of drilling well No. R. 25E., M. D. B. & M., Famoso Area Field, Kern Section 25 Legal description of lease.... (Attach map or plat to scale) property Location of Well: 990 330 feet North feet West along section line and (Direction) (Direction) property 25 Southeast at right angles to said line from the... corner of section. Elevation of ground above sea level 385. 9 feet to be submitted later which is feet above ground. Kelly bushing All depth measurements taken from top of.... (Derrick Floor, Rotary Table or Kelly Bushing) PROPOSED CASING PROGRAM IZE OF CASING GRADE AND TYPE воттом CEMENTING DEPTHS WEIGHT TOP 1000 *± H - 401000 1+ 11-3/4" Surface 23# 586511 or 58651± N-80 Smls. Note: 7" to be C. P. dd 711 26# 7050 7050 T Surface at base of fresh water 7850*± or 5900*± sands. 17# J-55 Smls 70301 710011

Map & Olcese or Vedder zones Intended zone or zones of completion:

Please send one copy of all notices to the following:

Moriqui Exploration Co. Kern County Land Co. 854 Gen*1 Petr. Bldg. 300 Montgomery St. 612 So. Flower St. San Francisco 4, Cal.

Los Angeles 17, Cal. Attn: Jas. A. Walker Bakersfield, Cal. Bakersfield, Cal. It is understood that if changes in this plan become necessary we are to notify you before running casing.

Easton & Sacre, Engineers

1716 Oak St.

Lee M.Ralph, Oil Divn. Mgr. Kern Co. Land Co. P. O. Box 380

114

Address 612 South Flower Street Los Angeles 17, California Telephone Number TUcker 1131

Moriqui Exploration Company